1. DATE - TIME GROUP	OCATION
-3 Jan 53 23/27/60Z	Bersstrom AFB. Austin, Texas
3. SOURCE	10. CONCLUSION
Airmann	WEATHER EFFECT ON RADAR
4. NUMBER OF OBJECTS	
One	
5. LENGTH OF OBSERVATION	11. BRIEF SUMMARY AND ANALYSIS
19 Minutes	Source shighted unidentified return on AM/NPM-1 GCA set,
6. TYPE OF OBSERVATION	operating on 30 and 15 mile range setting. Size of blip was 3/16" in width and 3/4" in length with fuzzy edges. Speed
Ground-Radar	from stationary to as fast or faster than jet a/c. No a/c
7. COURSE	in the vicinity and no other observations reported. Weather
Not Reported	data from weather Central at Asheville requested.
a. PHOTOS	1. This sighting was sent to Electronics (Mr. James) for
U Yes	analysis and the evaluation below was concluded.
Q No	2. Targets caused by WK conditions such as ice, clouds or rain clouds.
9. PHYSICAL EVIDENCE	rear crowds.
O Yes	



12th Strategic Fighter Wing

3

3

COMMENTS OF THE PREPARING OFFICER

T/Sgt Gerald V. Kelley, AF 11194087, has been performing the duties of AFSC 27272 Aircraft Landing Control Technician in the Airways and Air Communications Service Detachment 1921-1, 1921st AACS Squadron since August 1951 and is stated to be fully qualified by his commanding Officer.

The preparing officer does not know the observer personally.

EUGENE F. REDDEN 2/Lt. USAF Ass't Intelligence Officer

AFFROVED:

VICTOR W. H. RANKIN

Captain, USAF Intelligence Officer

12th Strategic Fighter Wing



DINCLASS:



IR-3-53

Almays and air commontgations carvide Dervice Tunally 1921-1

avelor and bodamin, jeas

UNCLASSIFIED

LO valuaty Lists

constant adjusting of unicantified largons

20:

Base intelligance bergstrom AF Base Austin, Texas


It is my opinion that the unidentified targets sighted by Technical Sergeant helley, Friday, 24 January 1953, was not one to malfunction of the radar set involved. However, I wish to make it clear
that I was not precent at the time of the sighting and did not observe the targets first-hand. My opinion is based purely on the testimony of Technical Sergeant Kelley and past canorience with the particalar radar set involved. No evidence of malfunction has been found
or noted since the incident.


Charles G. Reagor

Technical Capresentative

Gilrillan Bros. Inc

DOWNGRADED AT DECLASSIFICATION TO TEATER ASS.





Fq ATIC AFORM-ATIAE-5 Subject: (GMCL) Radar Sighting of Unknown Aerial Object
12Intel 360
1st Ind.

HEADQUARTERS, LIND AIR DIVISION, Bergstrom Air Force Base, Austin, Texas

TO: Air Technical Intelligence Center, Wright-Patterson Air Force Base, Ohio

Basic letter complied with.

FOR THE COLMANDING OFFICER:

1 Incl:

WILLARD D. HAGEY WOJG USAF

ASS'T ADJUTANT

This sighting correct as undersone

DECLASSIFIED AT 3 YEAR DOD DECLASSIFIED AFTER IN TOUR 5200.10 12.4125 1.5;





AIR TECHNICAL INTELLIGENCE CENTER WRIGHT-PATTERSON AIR FORCE BASE OHIO

UNCLASSIEIED

In reply refer to AFOIN-ATIAE-5

3 FEB 1953

SUBJECT: (UNCLASSIFIED) Radar Sighting of Unknown Aerial Object

TO:

Commanding Officer
Bergstrom Air Force Base
Austin, Texas

- 1. A GCA station at your base made electronic contact with unidentified aerial phenomena on or about 27 Jan 53, 1540CST, while monitoring local air traffic. In an attempt to uncover a logical explanation for such sightings, the Air Technical Intelligence Center has developed a questionnaire for sightings made by ground radar, one of which is an inclosure to this letter.
- 2. ATIC radar specialists have found the subject questionnaires of great value in attempting to explain radar contact with unknown flying objects when they are filled out completely and accurately by the radar personnel involved.
- 3. ATIC would, therefore, appreciate the completion and forward-ing of the Electronics Data Sheet at your earliest possible convenience.

FOR THE COMMANDING GENERAL

COORDINATION

INSERT
ORGAL CODE AND
FULL SIGNATURE

ATIA = 5 AFOIN309-53

H.6.9-1-1-1-1

ATIA = 5 AFOIN309-53

H.6.9-1-1-1

ATIA = 5 AFOIN309-53

H.6.9-1-1-1-1

ATIA = 5 AFOIN309-53

ATIA =

ROBERT G. B. D. D. H. Hajor, US/F Air Adj. Gan.

DOLVNGRADED AT 3 YEAR DECLASSIFIED AFTER 12 YEARS TO DOD DIR 5200.10 YEARS.

UNCLASSIFIED



tron:

8/5.

ELECTRONICS DATA SHEET (GROUND RADAR)

The purpose of this questionnaire is to provide technical data for evaluating the report of an unusual radar target or track. It is requested that it be completed as accurately as possible.


When not filled in, the form is Unclassified. The reporting officer will use his own judgement as to what degree of classification is required.

It is preferred that the answers to the questions be typewritten, however, if it will expedite the completion of the form, the answers may be printed in ink. If additional space is needed, use reverse side of form.

1. STATION OBSERVING TARGET: Bergstrom Ground Controlled A proach Organization Perestrom Air Force Base, Austin, Tex. Location	2. DATE OF THIS REPORT: 12 February 1953 Doy Month Year
3. DATE TARGET OBSERVED: 23 January 1953 Z Time Day Month Your Time-Local 150-1559 Time-Z 210-2159	4. NAME, RANK AND ORGANIZATION OF REPORTING OFFICER: Eugene F. Hedden 2/Lt. USAF 12th SFW Intelligence
5. EXACT LOCATION OF STATION (COORDINATES): 30 degrees 12 minutes north, 097 d	legrees 41 minutes west
6. OBSERVER DATE (LIST EACH OBSERVER): Name A B C D E	Ronk Duty Exp. in Rodor Aircr ft Landing T/Sgt Control Technician Four (4)
DOWNGRA DECLA	MAKING A VISUAL SIGHTING AND A BRIEF DESCRIPTION OF ADED AT 3 YE IN SSIFIED AT DOD DIR 0200.10 ACLASSIFIED NCLASSIFIED




e.	HAVE YOU HEARD OF ANYONE NOT AT THE RADAR STATION MAKING A VISUAL SIGHTING THE SAME TIME THE RADAR CONTACT WAS MADE? YES NO IF SO, GIVE NAME AND ADDRESS.	AT APPROXI	MATELY
9.	RADAR SCOPE PHOTOS:		
	IS RADAR EQUIPPED WITH A SCOPE CAMERA?		CI NO
	WAS CAMERA OPERATIONAL?		D NO
	WERE PRINTS OF THE SCOPE PHOTOS FORWARDED TO THE		Пио
	AIR TECHNICAL INTELLIGENCE CENTER?	YES	DNO
10.	WHAT WAS THE NUMBER OF THE TRACK?		
	WAS A PERMANENT PLOT MADE OF THE TRACK AT THE TIME OF THE OBSERVATION?	D YES	DO NO
11.	WERE AIRCRAFT SCRAMBLED TO INTERCEPT THE TARGET?	☐ YES	OF NO
	IF SO, WERE THE AIRCRAFT BEING OBSERVED ON THE SCOPE AT THE SAME TIME AS THE TARGET?	D YES	17.1972 2.00
12.	WERE ANY NEARBY RADAR INSTALLATIONS QUERIED WHETHER THEY HAD OBSERVED		LJ 140
• • • •	THE SAME TARGET OR TRACK?	[] YES	□ NO
	IF SO, WHICH STATIONS?		
13.	WAS THE TARGET OBSERVED ON SEARCH RADAR?)C) YES	□ но
	IF SO, WHAT IS THE NOMENCLATURE OF THE EQUIPMENT? ANAMEN-1		
	WAS THE TARGET OBSERVED ON HEIGHT FINDING RADAR?	TI VES	TIMO
14.	IF SO, WHAT IS THE NOMENCLATURE OF THE EQUIPMENT?	□ YES	שו מט
	,		
15.	HAVE THERE BEEN ANY RECENT MAINTENANCE DIFFICULTIES?	□ YES	D NO
	tF so, DESCRIBE. 3000 hour overhaul December 1952		
16.	WHAT TYPE MODULATOR (I.E., SPARK GAP, HARD TUBE, ETC.) IS USED IN THE RADAR E	QUIPMENT?	
	Hard Tube		
17	WAS THE AFC (AUTOMATIC FREQUENCY CONTROL) CIRCUIT OPERATING PROPERLY?	D VES	TINO
17.	COMMENTS: AFC was out of the circuit in off position at the time	of chaery	
18.	HAS INTERFERENCE FROM ANOTHER RADAR SET BEEN OBSERVED RECENTLY:	O YES	D NO
	No other cote in manufacture	The second	1077 ST000
	COMMENTS: UNCLASSIFIED DOWNGRADED AT DECLASSIFIED DOWN OF DECLASSIFIED DOWN DOWN DOWN DOWN DOWN DOWN DOWN DOW	2.VD.	
	DECLASSIFIED	AFTER TO	TERVAL
ATI	C FORM 332 (REVISED 25 NOV 1952)	R 5200.10	LEARS.




19.	ARE PERSONNEL FAMILIAR WITH THE	EFFECTS CAUSED BY	N INTERFERING SIGNAL? CLYES C	NO
	COMMENTS: Observer has o	bserved such effe	cts at other stations	
20.	ARE PERSONNEL FAMILIAR WITH THE E	FFECTS OF ANOMALO	US PROPAGATION (DUCTING EFFECTS)	AS THEY
21.	HAS ANOMALOUS PROPAGATION (DUCTI GROUND CLUTTER OF THIS RADAR AT COMMENTS: Unk unfamiliar wit	THIS SITE? [] YES [1 110	HE
	W16 W10 W11 D11 D11 D11 D11 D11 D11 D11 D11 D11			
22.	WAS ANOMALOUS PROPAGATION (DUCT! THE TIME THE TARGET WAS OBSERVED COMMENTS: See Pa		NG THE RANGE OF THE GROUND CLUT	TER AT
23.	HOW DID THE TARGET APPEAR IN SIZE	AND SHAPE AS COUPA	DED TO CONVENTIONAL MOCDARY	
20.	An roximately twice as large			ARGEISY
24.	PERFORMANCE OF TARGET:			
	a. REMAINED CONSISTENT IN SIZE	CE.	CHANGED SIZE RAPIDLY	O
	b. SPEED WAS CONSTANT		SPEED WAS VARIABLE	p
	. FOLLOWED CONSISTENT TRACK		APPEARED, DISAPPEARED, THEN REAPPEARED IN NEW LOCATION	p .
	d. FUZZY COMPARED TO AIRCRAFT	C). *	SHARP COMPARED TO KNOWN AIRCRAFT TARGET	D,***
	. SAME AS AIRCRAFT TARGET		•	
25.	WERE OTHER TARGETS (KNOWN) OBSERTIME AND AT THE SAME ALTITUDE AS T			ESAME
	IF SO, DESCRIBE. Normal flow of			O miles
	distart from target at altit			
26.	WHAT TYPE INDICATORS ("A" SCOPE, " PPI scope used (A & B)	"B" SCOPE, ETC.) WER	E USED TO FOLLOW THE TARGET?	
	DESCRIBE THE SIGNAL: Approxima	tely 2/3" X 1/1."	produced by rotating sweep.	
27.	WHAT WAS THE RADAR SCAN RATE?	(30) Thirty RE	M	
28.	Approximately 2800 mc	RANSMITTER?		
29.	DID ANY OF THE OBSERVERS HAVE AND IF YES, GIVE THEIR NAMES AND OPINION in all respects to normal tark	NS BELOW.	Target appeared	
		TINICI ACCUEIT		

UNCLASSIFIED OWNGRADED AT 3 YEAR INTERVALS
DOD DIR 5200.10

ATIC FORM 332 (REVISED 25 NOV 1952)







31. USE THIS SHEET FOR ANY COMMENTS, OPINIONS OR ADDITIONAL DATA NOT COVERED BY THE QUESTIONS.

Re. Par. 2hd Target appeared bright in center but fuzzy and diffused at the edges.

The. Par. 24 Constant surveillance was not maintained; however, the target when observed did appear in different rances and bearing when transition from 15 to 30 mile rance was accomplished; ovever, it is not known whether the target changed position in the marker in refere ce or by course to new position.

DOWNGRADED AT 3 YEAR INTERVALS;

DOD DIR 5200.10 YEARS



SIFICATION (// any) .

DISPOSITION FORM

UNCLASSIFIED



FILE NO.

SUBJECT

(Uncl) Radar Sighting of Unknown Flying Object

FROM ATTAE-5

DATE 5 Mer 53

COMMENT NO. 1

TO ATIAE-2

Attn: Mr. James

RU Lt Olsson/vs 65365/B 263/P A-30

- 1. Inclosed for your review and possible evaluation is a sighting of an unidentified object made at Bergstrom AFB, Texas, by an AN/NPM-1 GCA radar set. Only radar contact was made without any simultaneous visual observations.
- 2. ATIAE-5 sent the sighting station a copy of ATIC's Electronics Data Sheet which was worked out jointly by ATIAE and ATIAE-5. It is hoped that the information included thereon will afford a basis for a possible conclusion as to the cause of sighting.
- 3. While ATIAE-5 realizes the importance of comparing atmospheric conditions, i.e., temperature vs altitude, dewpoint vs altitude with the anonymous radar pickit takes up to a month to receive these data from the Asheville Weather Central. If possible, it is hoped that ATIAE-2 may be able to offer a possible solution in the interim.

1 Incl

File on Bergstrom AFB, Texas

Rulet m. alsom

A: E. J. RUPPELT, Capt, USAF

Chief, Aerial Phenomena Section

Electronics Branch

TO ATIAE-5

FROM ATIAE-2 DATE

Mr./Somes/leg 55170/Bldg 263A

- 1. Preliminary analysis indicates a strong possibility that targets were caused by weather conditions, possibly heavy rain clouds or ice-laden clouds.
 - 2. Additional weather data would be of considerable value.

Incl


DOWNGRADED AT "
DECLASSIFIF

Chief, Radiation Section

Electronics Branch

UNCLASSIFIED

DOWNGRADED AT 3 YEAR INTERVALS DECLASSIFIED AFTER 12 YEARS. DOD DIR 5200.10



BLUE TINT INDICATES AIR TRAFFIC CONTROLLED AREAS For pilot information see reverse side

Victor airway designations are shown along the radials of the omni range stations. Limits of these airways which are not indicated on this chart are 5 miles on either side of the radials.

SEARCH AND RESCUE

Search and Rescue Service is a life saving service provided through the combined efforts of the CAA, Air Force, and Coast Guard who are assisted by other organizations such as the Civil Air Patrol, Sheriffs Air Patrol, State Police, and such other agencies as may be available. It provides search, survival aid, and rescue of personnel of missing or crashed aircraft.

All you need to remember to obtain this valuable protection is:

- 1. File a Flight Plan with a CAA Airway Communications Station in person or by telephone or radio.
- 2. File an Arrival Report.

-3

E 707

RE

15.5

- 3. If you land at a location other than intended destination, report the landing to the nearest CAA Communications Station.
- 4. If you land enroute and are delayed more than an hour, report this information to the nearest communications station.
- Remember that if you fail to report within one hour after your E.T.A., a search will be started to locate you. If
 you fail to report within three hours after your E.T.A., the full facilities of the Search and Rescue Service will be
 activated.

Searches are expensive, they inconvenience other people, and on numerous occasions the lives of other pilots are sacrificed when searching for lost or overdue pilots. SO, FILE AN ARRIVAL REPORT!

GROUND TO AIR EMERGENCY CODE DISTRESS SIGNALS

REQUIRE DOCTOR, SERIOUS	REQUIRE SIGNAL LAMP WITH	REQUIRE FUEL AND OIL L
REQUIRE MEDICAL SUPPLIES	INDICATE DIRECTION TO PROCEED K	ALL WELL LL
UNABLE TO PHOCEEDX	AM PROCEEDING IN THIS DIRECTION	NON
REQUIRE FOOD AND WATER F	WILL ATTEMPT TAKE-OFF	YESY
AMMUNITION	AIRCRAFT SERIOUSLY DAMAGED L7	NOT UNDERSTOOD
REQUIRE MAP AND COMPASS	FROBABLY SAFE TO LAND HERE A	REQUIRE MECHANIC


INSTRUCTIONS:

- 1. Lay out symbols by using strips of fabric or parachutes, pieces of wood, stones, or any available material.
- Provide as much color contrast as possible between material used for symbols and background against which symbols are exposed.
- 3. Symbols should be at least 10 feet high or larger, if possible. Care should be taken to lay out symbols exactly as shown to avoid confusion with other symbols.
- 4. In addition to using symbols, every effort is to be made to attract attention by means of radio, flares, smoke, or other available means.
- 5. When ground is covered with snow, signals can be made by dragging, shoveling or tramping the snow. The depressed areas forming the symbols will appear to be black from the air.
- 6. Pilot should acknowledge message by rocking wings from side to side.

VISUAL EMERGENCY SIGNALS

HEED MEDICAL ASSISTANCE - DRIGENT USED ONLY WHEN LIFE IS AT STAKE	ALL OX -	CAN PROCEED SHORTLY	NEED MECHANICAL	DO NOT ATTEMPT
LIE PRONE	WAVE ONE ARM OVERHEAD	ONE ARM HORIZONTAL	HELP OR PARTS - LONG DELAY BOTH ARMS HORIZONTAL	BOTH ARMS WAVED ACROSS FACE
LAND HEME	USE DROP MESSAGE	OUR RECEIVER IS OPERATING	HEGATIVE (NO)	AFFIRMATIVE (YES)
BOTH ARMS FORWARD HORIZON- TALLY, SQUATTING AND POINTING IN DIRECTION OF LANDING - REPEAT	MAKE THROWING MOTION	CUP HANDS OVER EARS	WHITE CLOTH WAVED HOPIZONTALLY	WHITE CLOTH WAVED VESTICALL
PLANE ASANDONED	AFFIRMATIVE (YES)	NEGATIVE (NO)	HOW TO USE THEM IF YOU ARE FORCED DOWN AND ARE OF THE PILOT OF A RESCUE AIRPLAN ON THIS PAGE CAN HE USED TO TRE CIRCLES OVER YOUR LOCATION. ST. THE SIGNALS. HE SURE THAT THE IN- IS NOT CONFUSING. GO IMPORTS IT EACH SIGNAL UNTIL YOU ARE POSITE	E ABLE TO ATTRACT THE ATTENTION HE, THE BODY SIGNALS ILLUSTRATED ANSMIT MESSAGES TO HIM AS HE AND IN THE OPEN WHEN YOU MAKE ACKGROUND, AS SEEN FROM THE AIR THE MOTIONS SLOWLY AND REPEAT
BOTH ARMS VERTICAL	DIP NOSE OF PLANE SEVERAL TIMES	FISHTAIL PLANE	YOU.	AND DESIGNATION OF THE PARTY OF

VISUAL FLIGHT



PD SWITCHED BACK TO THREE ZERO RANGE WHERE OBJECT APPEARED ABOUT ONE EIGHT MILES OUT WITH ANOTHER SIMILAR OZJECT ABOUT ONE NINE MILES OUT JUST TO NORTH AND WEST AT BEARINGS OF TWO EIGHT FIVE DEGREES FOR THE IRST OBJECT AND BEARING OF TWO EIGHT SEVEN DEGREES FOR THE LATER PD OBJECTS REMAINED STATIONARY FOR ABOUT THREE OR FOUR MINUTES WHEN OPERATOR SWITCHED BACK TO ONE DIVE MILE RANGE PD TIME WAS ONE FIVE FOUR FIVE CST PD OPERATION WENT BACK TO THREE ZERO MILE RANGE PICKING UP OBJECT ABOUT TWO TWO MILES OUT ON THREE ONE ZERO BEARING PD OBJECT WAS STATIONARY SO OPERATOR CALLED BERGSTROM TOWER TO SEE IF THEY COULD SPOT OBJECT WITH FIELD GLASSES PD TOWER COULD NOT SEE OBJECT PD THIS WAS AT ONE FIVE ZERO IST PD BY THE TIME OPERATOR RETURNED TO SCOPE TARGET WAS LOCATED AT A BEARING OF TWO SEVEN FIVE DEGREES MOVED RAPIDLY ON A COURSE OF APPROX THREE SIX ZERO TO BEARING OF THREE TWO TWO DEGREES PD OBJECT HALTED REMAINING IN SIGHT FOR ABOUT THREE ZERO SECONDS AT ONE FIVE FIVE NINE OCLOCK CST PD PAR ACCORDING TO SHIFT CHIEF OPERATOR REPORTING OBJECT IS MOST EXPERIENCE OPERATOR WITH FOUR YEARS EXPERIENCE WITH AN AN PM DASH ONE REPEAT ANNPM DASH ONE GCA RADAR SET PD PAR CLOUDS SCATTERED AT TWO FIVE THOUSAND FEET CMA VISABILITY ONE FIVE MILES CMA TEMPERATURE SIX FIVE CMA DEW POINT THREE EIGHT CMA WIND NORTH NORTH WEST ONE THREE KNOTS GUSTS TWO THREE KNOTS AT ONE FIVE THREE ZERO HOURS CST PD PAR NOINTERCEPTION ATTEMPTED PD PAR TARK

GET APPEARED

LARGER THAN USUAL TARGETS EXCEPT LARGE FORMATIONS OF AIRCRAFT PD NO LARGE FOROATIONS OF AIRCRAFT IN VICINITY OF REPORTED TARGET OF BERGSTROM AREA PD END OF MESSAGE

DNCLASSIFIED

27/2347Z JAN JWSGM



Rodai sightly no misual contact de dilenception attempted-negative.

WPEØ25

YMA@13

WYC ØØ7

WDA267

JWFGM Ø72

PP JEDMH JEDEN JEDWP JWPHO 444

DE JWFGM Ø5Ø

P 272325Z ZNJ

FM CGADIV FOUR TWO BERGSTROM AFB TEXAS

TO JEPHQ/DIR OF INTELLIGENRE HQS USAF WASH DC

JEDWP/ATIC WRIGHT PATTERSON AFB OHIO

JEDEN/CG ENT AFB COLORADO SPRINGS COLO

JEDMH/CGSAC OFFUTT AFB NEBR

ONE TWO STRAT FTR WG INT 773 PD ATTN AT1AA-2C

FLYOERPT PD REPORT OF UNIDENTIFIED RADAR RETURN PD OPERATIO WAS ON

FLYOERPT PD REPORT OF UNIDENTIFIED RADAR RETURN PD OPERATIO WAS ON DUTY AT GCA STATION BERGSTROM AFE CMA COORDINATES THIRTY DEGREES TWELVE MINUTES NORTH DASH NINTY DASH SEVEN DEGREES FORTY DASH ONE MINUTES WEST CMA OPERATION AN ANN PM DASH ONE REPEAT ANNPM DASH ONE GCA RADAR SET PD WHILE ON THIRTY MILE RANGE SETTING TARGET APPEARED TWENTY ONE MILES DISTANT ON BEARING OF TWO NINE FIVE DEGREES MOVING RAPIDLY CMA AS FAST OF FASTER THAN JET AIRCRANT CMA TO BEARING OF TWO SEVEN' FIVE DEGREES WHERE IT STOPPED PD TIME WAS APPROX ONEFIVE FOUR ZERO CST PD OPERATOR SWITCHED TO ONE FIVE RANGE TO HANDLE LOCAL TRAFFIC PD

DOWNGRADED AT 3 YEAR INTERVALS; DECLASSIFIED AFTER 12 YEARS. DOD DIR 5200.10

JOINT MESSAGEFORM

COMMUNICATIONS CENTER NO.

FROM: (Originator)	SOISIOZ JAN 5	SECURITY CLASSIFICATION
CG ATIC	PRECEDENCE ACTION	tine INFORMATION
TO: CO DEND MIN DIVISION BEAUGO	DE BOOK MESSAGE	ORIGINAL MESSAGE
	MULTIPLE ADDRESS	CRYPTOPRECAUTION NO
	IDENTIFICATION	EFERS TO MESSAGE:
INFO:	INT-773	
PROM: APOIN-ATIAN-1-3-E		UNCLASSIEIED
Reference your message INT-77	75 reporting electronic pick-up o	of unidentified terget
approximately 27 Jan 55. ATI	C requests completion of AF Fore	a 112 on sighting plus
CONTRACTOR CARROLL A MARCHA 11A MARCHA		
	Date Chest which will he went he	
	Data Sheet which will be sent by	resil to your station
completion of an Electronics	Data Sheet which will be sent by lostion on date of sighting, mph	
completion of an Electronics Additionally, request clarifi		estimate of objects'
completion of an Electronics Additionally, request clarifi	loation on date of sighting, mph	estimate of objects'
completion of an Electronics Additionally, request clarifi speed and local jet air traff	lostion on date of sighting, sph Cic. If radar scope photos were	estimate of objects'
completion of an Electronics Additionally, request clarifi speed and local jet air traff Form 112.	ication on date of sighting, mph Cic. If reder scope photos were DOWNGRADED AT 3 YEAR	estimate of objects' taken, inclose with A
Additionally, request clarific speed and local jet mir traff. Form 112. In reply cite Project Blue Bo	lostion on date of sighting, sph Cic. If radar scope photos were	estimate of objects' taken, inclose with A
Additionally, request clarific speed and local jet mir traff. Form 112. In reply cite Project Blue Bo	ication on date of sighting, mph Cic. If reder scope photos were DOWNGRADED AT 3 YEAR	estimate of objects' taken, inclose with A
Additionally, request clarific speed and local jet mir traff. Form 112. In reply cite Project Blue Bo	cation on date of sighting, aph Cic. If reder scope photos were DOWNGRADED AT 3 YOUR DECLASSIFIED AFT DOD DIR 52	estimate of objects' taken, inclose with A
Additionally, request clarific speed and local jet mir traff. Form 112. In reply cite Project Blue Bo	ication on date of sighting, mph Cic. If reder scope photos were DOWNGRADED AT 3 YEAR	estimate of objects' taken, inclose with A EAR INTERVALS; 00.10 YEARS.
Additionally, request clarific speed and local jet air traff. Form 112. In reply cite Project Elue Econominations	Lostion on date of sighting, sph. Cic. If reder ecope photos were DOWNGRADED AT 3 YEARSIFIED AFTER DOD DIR 52	EAR INTERPREDATES: On 10 PAGES estimate of objects' teken, inclose with A EAR INTERPREDATES: 00.10 PAGES
Additionally, request clarific speed and local jet air traff. Form 112. In reply cite Project Blue Bo COORDINATION:	cation on date of sighting, aph Cic. If reder scope photos were DOWNGRADED AT 3 YOUR DECLASSIFIED AFT DOD DIR 52	EAR INTERPREDATES: On 10 PAGES estimate of objects' teken, inclose with A EAR INTERPREDATES: O0.10 PAGES
Additionally, request clarificationally, request clarifications and local jet air traffications lie. In reply cite Project Blue Bo COORDINATION: DRAFTER'S NAME (and signature, when required) Lt R. M. Classon/jos	Lostion on date of sighting, sph. Cic. If radar ecope photos were DOWNGRADED AT 3 YEAR DECLASSIFIED AFTE DOD DIR 52	EAR INTERNALS; OO.10 PAGES BRUNN. Naior. USAF

natai 30-filis

UNCLASSIFIED

UNCLASSIFIED

RE178M

WPB238

WYC158

JWFGM Ø7Ø

RR JEDWP

DE JWFGM Ø52

R Ø322Ø2Z

FM CGADIV 42 BERGSTROM AFB TEXAS

TO CGATIC WRIGHT PATTERSON AFB OHIO

AFOIN-ATIAE REF PROJECT BLUE BOOK PD AF FORM 112 FWD THROUGH CHANS
PD UNIDENTIFIED OVJ SIGHTED 23 JANUARY 1953 CMA 1540 TO 1559 CST PD
SPEED VARIED FROM STATIONARY TO AS FAST AS OR FASTER THAN JET ACFT PD
NO JET ACFT VICINITY OF TGT PD. NEGATIVE REPT OF LARGE FORMATIONS OF
ACFT IN BERGSTROM AREA PD RADAR SCOPE PHOTOS NOT MADE PD
03/2301Z FEB JWFGM

DOWNGRADED AT 3 YEAR INTERVALS; DECLASSIFIED AFTER 12 YEARS. DOD DIR 5200.10

cyl

United States

Report of the Observation of an Unidentified Flying Object

Austin, Texas

12th Strategic Fighter Wing

26 January 1953

23 January 1953

B-2

2/Lt. Eugene F. Redden

T/Sgt Gerald V. Kelley AF 11194087

AFL 200-5 FLYOBRPT 29 April 1952

While on duty at the GCA station, Bergstrom AFB, Austin, Texas, T/Sgt Gerald.

V. Kelley reported an unidentified radar return on an AN/NFM-1 GCA set. Sgt Kelley was operating on both the 30 and 15 mile range setting. The size of the blip was 3/16 inches in width and 3/4 inches in length with fuzzy edges. This object was observed between 15h0 and 1559 hours CST. The speed of the object varied from stationary to as fast or faster than jet aircraft. After it disappeared the area where it appeared was kept under surveillance for a period of about 5 minutes. No further returns were observed. No aircraft were in the vicinity, and no other observations of an object were reported.

The observer has not made a report of this incident to any other agency.

APPROVED:

Incl

Captain, USAE Intelligence Officer

12th Strategic Fighter Wing

2. Chart of Austin Area

^{1.} Statement of Radar Technical Representative

would indicate ground speeds in excess of 350 mph. He was producing a definite advance in position approximate speed, except that the return traversed a distance or approximate Constant surveillance was not maintained until approximately 1555CST since ten miles in a matter of seconds. T/Sgt Kelley had not realized the importance of this information and had not been made aware of pertinent regulations. All times are approximate as they were taken at the beginning and end of observations to the nearest five minutes until 1555CST after which the accuracy is to the nearest minute. All bearings were from the AT/MFM-1 unit to the center of the unit and were accurate to the degree of mechanical accuracy of the equipment and his skill at their operation. DOWNGRADED AT 3 YEAR INTERVALS; DECLASSIFIED AFTER 12 YEARS. MNCLASSIFIED DOD DIR 5200.10 Manager to the contract of the finite of the



12th Strategic Fighter Wing

While performing the duties of an Aircraft Landing Control Technician; in specific the operation of the Plan Position Indicator portion of ground radar set AN/NPM-1 on the 23rd of January 1953 at Bergstrom Air Force Base, Austin, Texas.

T/Sgt Gerald V. Kelley observed radar returns of an unusual nature under the following circumstances.

The first sighting was made at approximately 15h0CST while utilizing the thirty mile range of the Flan Position Indicator in attempt to locate a flight of F-Sh aircraft letting down to Bergstrom AFB and requesting the service of Ground Controlled Approach on arrival. T/Sgt Kelley observed a radar return of unusual proportions moving at a rapid rate of speed from an approximate bearing of 295 degrees in a southerly direction to an approximate bearing of 275 degrees at which time it ceased motion 21 miles from Bergstrom AFB for a short but undetermined length of time. It then moved in a westerly direction for approximately 2 statute miles and again remained stationary. His attention was then diverted by the normal flow of air traffic necessitating return to the 15 mile range for greater accuracy in control. In the interval he had contacted the Bergstrom control tower to advise of returns and request information on any large formation ilights in the area, receiving an acknowledgment and a negative report. On completion of pertinent traffic control at approximately 154505T he returned to the thirty mile range and observed two separate returns in stationary position, 285 degrees and 287 degrees, at 18 and 19 miles respectively for a short interval of time until necessary to return to the fifteen mile range. At this time he contacted Bergstrom control tower and requested that they scan the area with binoculars; a negative report of scan was received. At approximately 1550CST he again returned to the thirty mile range and observed a single stationary return 22 miles from Bergstrom AFB at bearing 310 degrees which remained stationary for the entire interval of observation until return to the fifteen mile range was once more necessary. After discharging traffic duties T/Sgt Kelley returned to the thirty mile range and observed a stationary return bearing 275 degrees approximately 17 miles from Bergstrom which remained stationary for a short time, then began a rapid movement on a course of O degrees to a bearing of 322 where it again ceased motion and remained stationary for approximately 30 seconds. It then faded and disappeared at approximately 1559CST. He kept constant surveillance from this time until approximately 1645CST with no further contact.

The return was similar to that which is produced by a large formation of aircraft, being of elliptical shape, approximately 3/1° in length and approximately 3/16° in width, being bright in the center and slightly diffused or ragged at the edges. The fast line constant circuit was in operation during all observations, all returns in question appeared to be of similar dimensions. When in motion the return appeared to be moving at a high rate of speed as the sweep trace was producing a definite advance in position at each revolution which in his experience would indicate ground speeds in excess of 350 mph. He was unable to determine the approximate speed, except that the return traversed a distance of approximately ten wiles in a matter of seconds.

Constant surveillance was not maintained until approximately 1555CST since T/Sgt Kelley had not realized the importance of this information and had not been made aware of pertinent regulations. All times are approximate as they were taken at the beginning and end of observations to the nearest five minutes until 1555CST after which the accuracy is to the nearest minute. All bearings were